

## Under Review Notification

**Raised By:** Steven Drouin

**Product #:** D350-794

**Date:** 19.08.01

**Product Name:** AUXILIARY FUEL TANK

Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	"Y" or "N" Required for Each Part Do not leave blank							Reserved ECN / URF Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
		DO NOT SHIP	Red Tag/Quarantine Stock	Advise Customers	Hold all Production	Re-Work Stock	IPP Under Review (Engineer Signoff Required.)	Put Product Specifications Under Review ("Bluefiles")		
D350-794-141	IIN-D350-794 Rev. H	Y	N	N	Y	N	Y	Y	19-832	CHG#005
D4464-041	D4464 Rev. I	Y	N	N	Y	N	Y	Y	19-832	Update Drawing
D350-794-111	IIN-D350-794 Rev. H	Y	N	N	Y	N	Y	Y	19-832	CHG#007
D4463-9/-11	D4463 Rev D	Y	N	N	Y	N	Y	Y	19-832	Update Drawing

**Description of Issue:**

One of the panel's Flat pattern (D4463-11) is causing a fit issue with the final assembly

<b>Distribution:</b>	VP Operations	Director of Engineering	Customer Support Manager	Technical Support
	Director of Operations	Chief Engineer	Production Engineers	Product Manager - Solutions Provider
	Director Quality Assurance	Engineering Project Managers	Production Planners	Supply Chain Director / Senior Buyer
	QC Coordinator	Engineering Clerk	Purchasing Manager	Marketing Eugene